



ALL PROCESSES MUST BE ROHS COMPLIANT.



CAUTION

THIS ASSEMBLY INCORPORATES
STATIC SENSITIVE DEVICES
ASSEMBLY AND HANDLING MUST BE DONE AT AN
APPROVED STATIC FREE STATION

CAUTION



SCINTERA

SC1894-DB1900A ASSEMBLY DRAWING

(RDB3.6 REV2)

SILK TOP

ASSY TOP

THIS ASSEMBLY INCORPORATES
STATIC SENSITIVE DEVICES
ASSEMBLY AND HANDLING MUST BE DONE AT AN
APPROVED STATIC FREE STATION

4	GND
5	RFOUT
6	GND
7	MGPO3
8	MGPO2
9	GND
10	MGPO1
11	MGPO0
12	GND
13	+3.3V
14	GND
15	+1.8V
16	GND



ASSY TOP


THIS ASSEMBLY INCORPORATES
STATIC SENSITIVE DEVICES
ASSEMBLY AND HANDLING MUST BE DONE AT AN
APPROVED STATIC FREE STATION

4	GND
	RFOUT
	GND
	MGPO3
	MGPO2
	GND
	MGPO1
	MGPO0
	GND
	+3.3V
	GND
	+1.8V
1	GND



ASSY TOP

ALL PROCESSES MUST BE ROHS COMPLIANT.



CAUTION

THIS ASSEMBLY INCORPORATES
STATIC SENSITIVE DEVICES
ASSEMBLY AND HANDLING MUST BE DONE AT AN
APPROVED STATIC FREE STATION

CAUTION



SCINTERA

SC1894–DB1900A ASSEMBLY DRAWING

(RDB3.6 REV2)

ASSY TOP