


ALL PROCESSES MUST BE ROHS COMPLIANT.




CAUTION

THIS ASSEMBLY INCORPORATES

STATIC SENSITIVE DEVICES

ASSEMBLY AND HANDLING MUST BE DONE AT AN
APPROVED STATIC FREE STATION

CAUTION



Maxim Integrated


SC1905-DB1900 ASSEMBLY DRAWING

(REVA)

SILK TOP

ASSY TOP

ALL PROCESSES MUST BE ROHS COMPLIANT.



CAUTION

THIS ASSEMBLY INCORPORATES
STATIC SENSITIVE DEVICES
ASSEMBLY AND HANDLING MUST BE DONE AT AN
APPROVED STATIC FREE STATION

CAUTION



GND 42
GND
GND

28	GND
	LOADENB
	SDO
	RESETN
	SSN
	SCLK
	WDTENB
	GND
	EXTCLKIN
	GND
	SDI
	DGPIN1
	STATO
	DGPINO
14	GND


Maxim Integrated

SC1905-DB1900 ASSEMBLY DRAWING

(REVA)

ASSY TOP

ALL PROCESSES MUST BE ROHS COMPLIANT.



CAUTION

THIS ASSEMBLY INCORPORATES
STATIC SENSITIVE DEVICES
ASSEMBLY AND HANDLING MUST BE DONE AT AN
APPROVED STATIC FREE STATION

CAUTION



GND 42
GND
GND

28	GND
	LOADENB
	SDO
	RESETN
	SSN
	SCLK
	WDTENB
	GND
	EXTCLKIN
	GND
	SDI
	DGPIN1
	STATO
	DGPI


Maxim Integrated

SC1905-DB1900 ASSEMBLY DRAWING

(REVA)

ASSY TOP

ALL PROCESSES MUST BE ROHS COMPLIANT.



CAUTION

THIS ASSEMBLY INCORPORATES
STATIC SENSITIVE DEVICES
ASSEMBLY AND HANDLING MUST BE DONE AT AN
APPROVED STATIC FREE STATION

CAUTION



GND 42
GND
GND

28	GND
	LOADENB
	SDO
	RESETN
	SSN
	SCLK
	WDTENB
	GND
	EXTCLKIN
	GND
	SDI
	DGPIN1
	STATO
	DGPINO
14	GND

Maxim Integrated

SC1905-DB1900 ASSEMBLY DRAWING

(REVA)

ASSY TOP