


ALL PROCESSES MUST BE ROHS COMPLIANT.



CAUTION


THIS ASSEMBLY INCORPORATES

STATIC SENSITIVE DEVICES

ASSEMBLY AND HANDLING MUST BE DONE AT AN

APPROVED STATIC FREE STATION

CAUTION



Maxim Integrated


SC1905-MB ASSEMBLY DRAWING

(RDB3.2 REVA)

SILK TOP

ASSY TOP

ALL PROCESSES MUST BE ROHS COMPLIANT.



CAUTION


THIS ASSEMBLY INCORPORATES

STATIC SENSITIVE DEVICES

ASSEMBLY AND HANDLING MUST BE DONE AT AN

APPROVED STATIC FREE STATION

CAUTION




Maxim Integrated

SC1905-MB ASSEMBLY DRAWING

(RDB3.2 REVA)

ASSY TOP

ALL PROCESSES MUST BE ROHS COMPLIANT.



CAUTION


THIS ASSEMBLY INCORPORATES

STATIC SENSITIVE DEVICES

ASSEMBLY AND HANDLING MUST BE DONE AT AN

APPROVED STATIC FREE STATION

CAUTION




Maxim Integrated

SC1905-MB ASSEMBLY DRAWING

(RDB3.2 REVA)

ASSY TOP

ALL PROCESSES MUST BE ROHS COMPLIANT.



CAUTION


THIS ASSEMBLY INCORPORATES

STATIC SENSITIVE DEVICES

ASSEMBLY AND HANDLING MUST BE DONE AT AN

APPROVED STATIC FREE STATION

CAUTION



Maxim Integrated

SC1905-MB ASSEMBLY DRAWING

(RDB3.2 REVA)

ASSY TOP