

Gerber Setup

General	Layers	Drill Drawing	Apertures	Advanced
Layers To Plot				
Extension	Layer Name	Plot	Mirror	
-GTO	Silkscreen Top	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
-GTP	Paste Mask Top	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
-GTS	Solder Mask Top	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
-GTL	L1 TOP	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
-G1	L2 GND	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
-G2	L3 PWR	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
-GBL	L4 BOT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
-GBS	Solder Mask Bottom	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
-GBP	Paste Mask Bottom	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
-GBO	Silkscreen Bottom	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
-GM1	Assembly Drawing Top	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
-GM18	MECH	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
-GKO	Keep-Out Layer	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
-GPT	Top Pad Master	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
-GPB	Bottom Pad Master	<input checked="" type="checkbox"/>	<input type="checkbox"/>	