

Serial Port Expansion Board Project (11/15/04)

TINIs400 rev B Errata (11/15/2004)

1. The external interrupt 0 circuit is not properly connected to CPLD U12. A jumper wire must be added between J4.2 and J17 (pad *opposite* the side connected to U8.8).

TINIm400 Serial Expansion Board rev A Errata

1. Place a jumper wire between J1.15 and J1.20.