



Product/Process Change Notice - PCN 19_0091 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. **Any inquiries or requests with this PCN (additional data or samples) must be sent to ADI within 30 days of publication date.** ADI contact information is listed below.

PCN Title: Moisture Sensitivity Level Rating Change for HMC487

Publication Date: 16-May-2019

Effectivity Date: 16-May-2019 *(the earliest date that a customer could expect to receive changed material)*

Revision Description:
Initial Release.

Description Of Change:

Moisture Sensitivity Level (MSL) rating is being changed from MSL1 to MSL3 for HMC487.

Reason For Change:

The MSL rating is being changed due to package-die interaction.

Impact of the change (positive or negative) on fit, form, function & reliability:

This change does not impact fit, form, function or reliability of the products.

Summary of Supporting Information:

Qualification has been performed per Industry Standard Test Methods. See attached Qualification Results Summary.

Supporting Documents

Attachment 1: Type: Qualification Results Summary

ADI_PCN_19_0091_Rev_-_Qualification Results Summary for the HMC487 LFCSP Part.pdf

For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives.

Americas:
PCN_Americas@analog.com

Europe:
PCN_Europe@analog.com

Japan:
PCN_Japan@analog.com

Rest of Asia:
PCN_ROA@analog.com

Appendix A - Affected ADI Models				
Added Parts On This Revision - Product Family / Model Number (2)				
HMC487 / HMC487LP5E	HMC487 / HMC487LP5ETR			

Appendix B - Revision History			
Rev	Publish Date	Effectivity Date	Rev Description
Rev. -	16-May-2019	16-May-2019	Initial Release.

Analog Devices, Inc.

DocId:6702 Parent DocId:None Layout Rev:7